

SERVICE BULLETIN





























BRIGGS & STRATTON TECHNOLOGIES

Automotive Systems Group

TO ALL AUTHORIZED SERVICE ACCOUNTS
AS-1975 MANUAL OWNERS
SUBJECT 1993 Saturn Station Wagon

No. AS-1131
DATE 10-1-92
FILE IN Bulletin Binder

With the introduction of the new 1993 Saturn Station Wagon in fall of 1992. Please update your Saturn Service Kit #701678, with the following two new part numbers; 321976 Pawl, 46949 Return Spring. The addition of these parts to your kit, will assure your readiness to properly service all Saturn locks.

				 321976 TAILGATE LOCK PAWL	 46949 TAILGATE LOCK RETURN SPRING	
 47615	 46906					
 321688	 321691	 321692	 94566	 380906	 380540	
 380706	 380706	 380706	 94431	 94431	 83331	
 321687	 321687	 321899	 321899	 594753	 46912	
 321761	 321762	 321763	 321764	 46890	 46859	

SATURN SERVICE KIT #701678

Briggs & Stratton Corporation
 Fred Kosloske
 Supervisor Service