

SERVICE BULLETIN

BRIGGS & STRATTON TECHNOLOGIES




Automotive Systems Group

TO CENTRAL SERVICE DISTRIBUTORS
AUTHORIZED AUTOMOTIVE SERVICE DISTRIBUTORS
AS-1975 MANUAL OWNERS
SUBJECT 1987 GM C-K Full Size Pickup Introduced
February 1987


No. AS-1102
DATE 3/1/88
FILE IN Bulletin
Binder

The subject vehicle is equipped with a door lock that mounts in a paddle style door handle. The lock is retained in the handle by a spring loaded retainer that is part of the lock case. A rubber gasket scalp is used over the cap to protect the lock and handle from water.

Service Package #700639 has been created for service repair.

Lock Service	Cylinder	Case Cap
 700639 D-GRV.	 591301	 321598 47603 (Scalp)

For Coded replacement use Part #700851



BRIGGS & STRATTON TECHNOLOGIES

CEL/bjo