


TO CENTRAL SERVICE DISTRIBUTORS
AUTHORIZED AUTOMOTIVE SERVICE DISTRIBUTORS
AS-1975 MANUAL OWNERS
SUBJECT GM Rear Compartment Shaft and Washer Assembly

No. AS-1085
DATE 11/15/83
FILE IN Bulletin
Binder



Confusion in the field concerning identification of Lock Shafts has come to our attention.

In our Annual Parts Catalog we list the O.E.M. part numbers whenever available.

In the case of the subject assemblies you will find that the O.E.M. number does not match the number stamped on the shaft.

Example: 1983 Page 12
591109 - 20023789

The shaft in this assembly carries #23791. GM using only the last five (5) digits of their part number.

Remember the single shaft was used in Production first, then the Safety Washer was added, but the Shaft Component number remains the same within the Assembly and the Assembly takes on a number of its own.

BRIGGS & STRATTON CORPORATION

L. B. White
Service Sales Manager
Automotive Lock Division

LBW: bjo