




**TO** CENTRAL SERVICE DISTRIBUTORS  
AUTHORIZED AUTOMOTIVE SERVICE DISTRIBUTORS  
AS-1975 MANUAL OWNERS  
**SUBJECT** CHANGE MID-YEAR DOOR LOCK CYLINDERS 1988½  
CHEVROLET CORSICA MODELS

**No.** AS-1107  
**DATE** 12/16/88  
**FILE IN** Bulletin  
Binder


General Motors has changed door lock cylinders from standard short length cylinders to medium length cylinders. The change is being made to improve key effort.

## ORIGINAL LISTINGS

**Coded**  
608170



**Lock Service Package**  
607868



**Pawls - RH**  
321372




**Pawls - LH**  
321373




## FOR SERVICE NOW

**Coded**  
608215



**Lock Service Package**  
608317



**New Pawls - RH**  
321766



**New Pawls - LH**  
321767

