

# SERVICE BULLETIN

BRIGGS & STRATTON TECHNOLOGIES




Automotive Systems Group

**TO** CENTRAL SERVICE DISTRIBUTORS  
AUTHORIZED AUTOMOTIVE SERVICE DISTRIBUTORS  
AS-1975 MANUAL OWNERS  
**SUBJECT** 1987 GM C-K Full Size Pickup Introduced  
February 1987


**No.** AS-1102  
**DATE** 3/1/88  
**FILE IN** Bulletin  
Binder

The subject vehicle is equipped with a door lock that mounts in a paddle style door handle. The lock is retained in the handle by a spring loaded retainer that is part of the lock case. A rubber gasket scalp is used over the cap to protect the lock and handle from water.

Service Package #700639 has been created for service repair.

Lock Service	Cylinder	Case Cap
 700639 D-GRV.	 591301	 321598 47603 (Scalp)

For Coded replacement use Part #700851



BRIGGS & STRATTON TECHNOLOGIES

CEL/bjo