

SERVICE


BRIGGS & STRATTON

BULLETIN

TO CENTRAL SERVICE DISTRIBUTORS
ALL AUTHORIZED SERVICE ACCOUNTS
AS-1975 MANUAL OWNERS

SUBJECT 700260 Lock Service Package
American Motors T.G. 1985

No. AS 1096
DATE 4/1/87
FILE IN Bulletin
Binder




The subject lock is a standard assembly incorporating new parts; primarily the **lock cylinder** and the **pawl**.

This is a **Side-Bar** construction similar to 607838 used on **Gremlin, Pacer and Station Wagon** vehicles from 1974 thru 1984.

The servicing of this assembly has been relatively simple with the most difficult job of staking the production caps.

With this new assembly you will have to drill a hole in the pawl for the roll pin that holds the pawl to the cylinder.

The following illustration shows how.



BRIGGS & STRATTON CORPORATION

Service Department

JGS/gp