



SERVICE BULLETIN

| | | | |
|----------|---------------------------------|----------|-----------------|
| TO: | AS-1975 MANUAL OWNERS/AWLD DIST | NO. | AS-1304 |
| SUBJECT: | H2 & GMT610 Key Code Series | DATE: | 1/7/2008 |
| | | FILE IN: | BULLETIN BINDER |

The key code series is listed incorrectly in the 2008 Lock & Key catalog for the Chevrolet Express, GMC Savana and H2. The correct key code series is S0004-S711K and **NOT** the G0001-G3631 as listed in the catalog.

The keys did change to 93 Groove Circle Plus technology but the key code series did not change as a result of the secondary lock environment (length of locks and the number of tumblers required).

This correction will be made in future editions of the Lock & Key catalog.